

## 2016 - 2018 Cadillac CTS-V: Service Bulletin: #20-NA-207: Information on Malfunction Indicator Lamp (MIL) Illuminated - DTC P0333 Set - (Oct 6, 2020)

### #20-NA-207: Information on Malfunction Indicator Lamp (MIL) Illuminated - DTC P0333 Set - (Oct 6, 2020)

**Subject:** Information on Malfunction Indicator Lamp  
(MIL) Illuminated - DTC P0333 Set

This bulletin replaces PIP5576. Please discard PIP5576.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmissi
		from	to	from	to		on:
<b>Cadillac</b>	CTS-V	2016	2018	All	All	6.2L (LT4)	All
	Escalade	2015	2018	All	All	6.2L (L86)	All
<b>Chevrolet</b>	Camaro	2016	2018	All	All	6.2L (LT1, LT4)	All
	Corvette	2016	2018	All	All	6.2L (LT1, LT4, LT5)	All
	Silverado	2014	2018	All	All	4.3L, 5.3L, 6.2L (L83, L8B, L86, LV1, LV3)	All
<b>GMC</b>	Suburban	2015	2019	All	All	5.3L (L83)	All
	Tahoe	2015	2019	All	All	5.3L (L83)	All
	Sierra	2014	2018	All	All	4.3L, 5.3L, 6.2L (L83, L86, LV1, LV3)	All
	Yukon Models	2015	2018	All	All	5.3L, 6.2L (L83, L86)	All

#### *Involved Region or Country*

North America, Europe, Russia, Middle East, Israel, Chile, Colombia, Ecuador, Venezuela, Japan, GM Korea Company, China, Taiwan, Thailand, Singapore, Philippines, Other Africa  
Some customers may comment that the MIL is illuminated when shifting the transmission from Park.

#### *Condition*

<i>Cause</i>	Some technicians may find DTC P0333 (Knock Sensor Circuit High Voltage Bank 2) set in the Engine Control Module (ECM).
<i>Correction</i>	DTC P0333 can set due to voltage from the transmission park/neutral signal 1 circuit bleeding into the knock sensor system circuits. To correct this condition, follow service information for diagnostic code P0333. If service information does not isolate the concern, then inspect the K20 ECM X2 electrical connector for debris, connector and/or terminal concerns.
<i>Version</i>	1
<i>Modified</i>	Released October 06, 2020

Online URL: <https://cadillacvnet.com/knowledge-base/article.php?id=36>