2020 - 2021 Cadillac CT4-V and CT5-V: Service Bulletin: #PIT5796A: Drivers Memory Seat Does Not Adjust / Move To Its Full Travel - (Feb 5, 2021)

## **#PIT5796A:** Drivers Memory Seat Does Not Adjust / Move To Its Full Travel - (Feb 5, 2021)

Subject: Drivers Memory Seat Does Not Adjust / Move To Its Full Travel

Brand:	Model:	Model Year:		VI	VIN:		Transmi
		from	to	from	to		ssion:
Buick	Envisio n	2021		All	All	All	All
Cadillac	CT4	2020-2021		All	All	All	All
Cadillac	CT5	2020-2021		All	All	All	All
Cadillac	Escalad e Models	2021		All	All	All	All
Chevrol et	Corvett e	2020-2021		All	All	All	All
Chevrol et	Suburba n	2021		All	All	All	All
Chevrol et	Tahoe	2021		All	All	All	All
GMC	Yukon Models	2021		All	All	All	All

Involved Region or Country North America

**Condition** Some customers may comment that

when they use the driver's power seat

switch, the seat does not move or does not move to its full travel.

Examples, the driver's seat back will not recline or the seat will not move

to the full rearward or forward

position.

Cause This concern could be caused by a

software issue with the K40D Driver's Seat Adjuster Memory

Module.

## Online URL:

https://www.cadillacvnet.com/knowledge-base/article/2020-2021-cadillac-ct4-v-and-ct5-v-service-bulletin-pit5796a-drivers-memory-seat-does-not-adjust-move-to-its-full-travel-feb-5-2021-53.html