


2021 Cadillac CT5 RWD L4-2.0L Turbo

## INSTRUMENT PANEL CENTER TRIM PAD REPLACEMENT

Document ID: 5319934



Callout	Component Name
<b>Preliminary Procedures</b>  1. Instrument Panel Cluster Trim Plate Applique Replacement 2. Instrument Panel Instrument Cluster Hood Replacement	
1	Instrument Panel Center Trim Pad Bolt <b>Caution:</b> Refer to Fastener Caution. <b>2.5Nm (22 lb in)</b>
2	Instrument Panel Center Trim Pad <b>Procedure</b> Using a flat-bladed plastic trim tool, release the retaining clips.