

2017 Cadillac CTS-V: GM TechLink: Supercharger Idler Pulley Sounds

2017 Cadillac CTS-V: Supercharger Idler Pulley Sounds

March 29, 2017
GM TechLink

A scraping or moaning sound may be heard from the supercharger idler pulley on some 2017 Cadillac CTS-V, Corvette; and 2017 - 2018 Camaro models equipped with the supercharged 6.2L V8 engine (RPO LT4). The sound will be most noticeable when the engine is idling.

This condition has the following VIN breakpoints:

| Model | From VIN | To VIN |
|---------------|----------|----------|
| 2017 CTS-V | H0194673 | H0196684 |
| 2017 Corvette | H5605159 | H5605593 |
| 2017 Camaro | H0197262 | H0196702 |
| 2018 Camaro | J0100002 | J0100018 |

If the pulley sound is found, replace the idler pulley assembly. (Fig. 12)




Fig. 12

– *Thanks to Richard Renshaw*

Online URL:

<https://www.cadillacvnet.com/knowledge-base/article/2017-cadillac-cts-v-gm-techlink-supercharger-idler-pulley-sounds-29.html>