

2017 Cadillac CTS-V: GM TechLink: Supercharger Idler Pulley Sounds

29 May 10, 2020 [Engine](#) 0 3019

2017 Cadillac CTS-V: Supercharger Idler Pulley Sounds

March 29, 2017

GM TechLink

A scraping or moaning sound may be heard from the supercharger idler pulley on some 2017 Cadillac CTS-V, Corvette; and 2017 - 2018 Camaro models equipped with the supercharged 6.2L V8 engine (RPO LT4). The sound will be most noticeable when the engine is idling.

This condition has the following VIN breakpoints:

Model	From VIN	To VIN
2017 CTS-V	H0194673	H0196684
2017 Corvette	H5605159	H5605593
2017 Camaro	H0197262	H0196702
2018 Camaro	J0100002	J0100018

If the pulley sound is found, replace the idler pulley assembly. (Fig. 12)




Fig. 12

– Thanks to Richard Renshaw

Online URL:

<https://www.cadillacvnet.com/knowledge-base/article/2017-cadillac-cts-v-gm-techlink-supercharger-idler-pulley-sounds-29.html>