

# 2016 - 2018 Cadillac ATS-V CTS-V: Service Bulletin: #16-NA-059: Staining/Discoloring to Brake Caliper Paint - (Oct 14, 2020)

## #16-NA-059: Staining/Discoloring to Brake Caliper Paint - (Oct 14, 2020)

Subject: Staining/Discoloring to Brake Caliper Paint					
Brand:	Model:	Model Year: from	to	VIN: from	Engine: Transmi ssion: to
Cadillac	ATS-V	2016	2018	—	All
	CTS-V	2016	2018		All
Chevrolet	Camaro	2012	2021		
t	Corvette	2014	2020		

### *Involved Region or Country*

North America, Europe, Russia, Middle East, Israel, Argentina, Brazil, Bolivia, Chile, Colombia, Ecuador, Paraguay, Peru, Uruguay, Japan, GM Korea Company, China, Taiwan, Philippines

### *Condition*



Some customers may comment on a discoloration or black stain on the paint of the brake calipers.


### *Cause*

This may be caused by high brake pad temperatures during aggressive driving or track event tarnishing the caliper paint.

### **Correction**

**Important:** Do *NOT* replace the brake calipers for this condition.

This is not a defect in the paint or the caliper.



(1)

Not cleaned using mild polishing compound

(2)

Cleaned using mild polishing compound

If the customer wishes to have the black stain removed, a very mild polishing compound can be used to remove the stain.

**Important:** Do NOT use harsh chemicals or brake cleaner to attempt

to remove the stain. This could damage the paint on the caliper.

<i>Version</i>	3
<i>Modified</i>	May 30, 2017 – Updated the Models and Model Years.
	October 14, 2020 – Updated the Models, Model Years and updated formatting to remove Attention statement and add the Involved Region or Country section.

Online URL:

<https://www.cadillacvnet.com/knowledge-base/article/2016-2018-cadillac-ats-v-cts-v-service-bulletin-16-na-059-staining-discoloring-to-brake-caliper-paint-oct-14-2020-39.html>