


YMMS: 2023 Cadillac CT4 V Blackwing  
Engine: 3.6L Eng  
VIN:

Dec 10, 2023  
License:  
Odometer:

## REPAIR INSTRUCTIONS > PASSENGER COMPARTMENT AIR FILTER REPLACEMENT > REMOVAL PROCEDURE

1. Open the instrument panel compartment door.




Courtesy of GENERAL MOTORS COMPANY

- 2.

Disconnect the instrument panel compartment door dampener detent (1) from the instrument panel compartment door.


3. Squeeze the sides of the instrument panel compartment door and lower the instrument panel compartment door past the stops.



Courtesy of GENERAL MOTORS COMPANY

4.

Passenger Compartment Air Filter Cover (1) - Remove




Courtesy of GENERAL MOTORS COMPANY

5.

Passenger Compartment Air Filter (1) - Remove


**REPAIR INSTRUCTIONS > PASSENGER COMPARTMENT AIR FILTER REPLACEMENT > INSTALLATION PROCEDURE**



Courtesy of GENERAL MOTORS COMPANY

1.

Install the passenger compartment air filter (1) with the air flow directional arrow found on the filter pointing down.




Courtesy of GENERAL MOTORS COMPANY

2.

Passenger Compartment Air Filter Cover (1) - Install

3. Squeeze the sides of the instrument panel compartment door and move the instrument panel compartment door stops into the channels.



Courtesy of GENERAL MOTORS COMPANY

4.

Connect the instrument panel compartment door dampener detent (1) onto the instrument panel compartment door.

5. Close the instrument panel compartment door.